



AMERICAN CAN

NEW ORLEANS, LOUISIANA

United Restoration was contracted to repair/restore the exterior façade of the once American Can Factory in New Orleans, Louisiana. The property consisted of two structure types: concrete and brick veneer with large steel windows and multi-wythe brick walls with wood windows. In an effort to control costs and satisfy the historical requirements, the owner selected to restore the original steel windows in place. Over a period of 2-3 years, United Restoration meticulously removed layers of failed paint, repaired the original steel window components, and installed new high-performance coating to all steel windows, and replaced all existing sealants within the window systems. Additional façade repairs included: concrete spall repairs, façade cleaning, and application of a breathable exterior coating.



SERVICES PROVIDED

- Concrete / Structural Restoration
- Exterior Painting / Coating
- Façade Restoration
- Historic Restoration
- Window Restoration

PROJECT INFO

- Duration 27 Months
- Completed July 2022
- Contract \$ 3,570,599
- Client Audubon Communities

CONTACT UNITED

- ☎ (770) 460-9606
- ✉ info@urpinc.com
- 🌐 www.urpinc.com

